

CSC-Tool Laser Sensor Vehicle Coverage V57



Document version 1.0

Basic requirement: mmPC, mm77, mm66, mm56, mm42SE

Glossar: calibration/adjustment required:

- # 1 after removal/installation laser sensor
- # 2 faultcode
- # 3 suspension structure modified / adjusted
- # 4 Lock carrier loosened / wrongly adjusted
- # 5 bumper bracket loosened / wrongly adjusted
- # 6 damage of bumper bracket / lock carrier

Sep 19

status version	manufacturer	model	year	calibration required by	available since version	equipment for positioning		equipment for adjustment
						CSC-Tool	system mount	calibration panel
new in V57	Audi	A6 (4A)	2018 -	#1, #2, #3, #4, #5, #6	56	yes	yes	CSC 5-01
new in V57	Audi	A7 (4K)	2018 -	#1, #2, #3, #4, #5, #6	56	yes	yes	CSC 5-01
new in V57	Audi	A8 (4N)	2017 -	#1, #2, #3, #4, #5, #6	56	yes	yes	CSC 5-01
new in V57	Audi	Q8 (4M)	2018 -	#1, #2, #3, #4, #5, #6	56	yes	yes	CSC 5-01