



Table of Contents:

1	Vehicle Coverage Front Camera V58	3
2	Vehicle Coverage Rear View Camera V58	7
3	Vehicle Coverage Area View Camera V58	8
4	Vehicle Coverage Front Radar V58	9
5	Vehicle Coverage Rear Radar V58	12
6	Vehicle Coverage Laser Sensor V58	13

status version	manufacturer	model	year	calibration required by	calibration type	available since version	notes	CSC-Tool	equipment
									panel
	VW	CC (35)	2012 - 2017	#1, #2, #3, #5, #6	static	45		yes	CSC 1-01
	VW	Crafter (2E/2F)	2014 - 2017	#1, #2, #3, #5, #6	static	54		yes	CSC 1-02
	VW	Crafter (SZ/SY)	2017 -	#1, #2, #3, #5, #6	static	52		yes	CSC 1-01
	VW	Golf 7 (5G/BA)	2012 -	#1, #2, #3, #5, #6	static	45		yes	CSC 1-01
	VW	Golf 7 Sportsvan (AM)	2014 -	#1, #2, #3, #5, #6	static	45		yes	CSC 1-01
	VW	Passat (36)	2010 - 2014	#1, #2, #3, #5, #6	static	45		yes	CSC 1-01
	VW	Passat (3C)	2005 - 2010	#1, #2, #3, #5, #6	static	45		yes	CSC 1-01
	VW	Passat (3G)	2015 - 2019	#1, #2, #3, #5, #6	static	48		yes	CSC 1-01
new in V58	VW	Passat (CB)	2019 -	#1, #2, #3, #5, #6	static	58		yes	CSC 1-01
	VW	Passat CC (35)	2008 - 2012	#1, #2, #3, #5, #6	static	45		yes	CSC 1-01
	VW	Phaeton (3D)	2010 - 2016	#1, #2, #3, #5, #6	static	50		yes	CSC 1-01
	VW	Sharan (7N)	2010 -	#1, #2, #3, #5, #6	static	47		yes	CSC 1-01
	VW	T-Cross (C1)	2019 -	#1, #2, #3, #5, #6	static	57		yes	CSC 1-01
	VW	Tiguan (5N)	2011 - 2016	#1, #2, #3, #5, #6	static	47		yes	CSC 1-01
	VW	Tiguan (AD)	2016 -	#1, #2, #3, #5, #6	static	51		yes	CSC 1-01
	VW	Touareg (7P)	2010 - 2018	#1, #2, #3, #5, #6	static	45		yes	CSC 1-01
	VW	Touareg (CR)	2018 -	#1, #2, #3, #5, #6	static	56		yes	CSC 1-01
	VW	Touran (1T3)	2010 - 2015	#1, #2, #3, #5, #6	static	45		yes	CSC 1-01
	VW	Touran (5T)	2015 -	#1, #2, #3, #5, #6	static	50		yes	CSC 1-01
	VW	T-Roc (A1)	2017 -	#1, #2, #3, #5, #6	static	55		yes	CSC 1-01
	VW	Passat (3C)	2005 - 2010	#1, #2, #3, #5, #6	static	53	from 2018 Adapter SGW FCA (8PZ 015 269-011) required	yes	CSC 1-16

3 Vehicle Coverage Area View Camera V58

basic requirement: mega macs PC, 77, 66, 56, 42SE

calibration required:

- #1 change one or more cameras
- #2 change camera ECU
- #3 camera element modification/adjustment
- #4 chassis modification/adjustment
- #5 incorrect image presentation
- #6 fault code

status version	manufacturer	model	year	calibration required by	calibration type	available since version	CSC-Tool	equipment for positioning		equipment for adjustment		
								Rear Cam Kit I Basic Profile	Rear Cam Kit I Addition Profile	Rear Cam Kit I Basic Panel	Rear Cam Kit I Addition Panel	Calibration Mate
	Audi	A4 (8W)	2015 -	#1, #2, #3, #4, #5, #6	static	51	yes	no	no	no	no	CSC 3-02
	Audi	A5 (F5)	2016 -	#1, #2, #3, #4, #5, #6	static	52	yes	no	no	no	no	CSC 3-02
	Audi	A6 (4A)	2018 -	#1, #2, #3, #4, #5, #6	static	55	yes	no	no	no	no	CSC 3-02
	Audi	A7 (4G)	2010 -	#1, #2, #3, #4, #5, #6	static	51	yes	yes	yes	CSC 2-01	CSC 3-01	CSC 3-02
	Audi	A7 (4K)	2018 -	#1, #2, #3, #4, #5, #6	static	55	yes	no	no	no	no	CSC 3-02
	Audi	A8 (4N)	2017 -	#1, #2, #3, #4, #5, #6	static	55	yes	no	no	no	no	CSC 3-02
new in V58	Audi	e-tron (GE)	2019 -	#1, #2, #3, #4, #5, #6	static	58	yes	no	no	no	no	CSC 3-02
	Audi	Q3 (F3)	2018 -	#1, #2, #3, #4, #5, #6	static	56	yes	no	no	no	no	CSC 3-02
	Audi	Q5 (FY)	2017 -	#1, #2, #3, #4, #5, #6	static	52	yes	no	no	no	no	CSC 3-02
	Audi	Q7 (4M)	2015 -	#1, #2, #3, #4, #5, #6	static	51	yes	no	no	no	no	CSC 3-02
	BMW	1er (F20/F21)	2011 - 2019	#1, #2, #3, #5, #6	dynamic	49	no	no	no	no	no	no
	BMW	1er (F40)	2019 -	#1, #2, #3, #5, #6	dynamic	57	no	no	no	no	no	no
	BMW	2er (F45/F46/F22/F23)	2014 -	#1, #2, #3, #5, #6	dynamic	50	no	no	no	no	no	no
	BMW	3er (F30/F31/F34/F80)	2011 -	#1, #2, #3, #5, #6	dynamic	49	no	no	no	no	no	no
	BMW	4er (F32/F33/F36/F82/F83)	2013 -	#1, #2, #3, #5, #6	dynamic	49	no	no	no	no	no	no
	BMW	5er (F07/F10/F11/F18)	2010 - 2017	#1, #2, #3, #5, #6	dynamic	50	no	no	no	no	no	no
	BMW	6er (F06/F12/F13)	2011 -	#1, #2, #3, #5, #6	dynamic	49	no	no	no	no	no	no
	BMW	7er (F01/F02/F03/F04)	2008 - 2015	#1, #2, #3, #5, #6	dynamic	49	no	no	no	no	no	no
	BMW	i8 (I12)	2014 -	#1, #2, #3, #5, #6	dynamic	51	no	no	no	no	no	no
	BMW	i8 Roadster (I15)	2018 -	#1, #2, #3, #5, #6	dynamic	55	no	no	no	no	no	no
	BMW	X1 (F48)	2015 -	#1, #2, #3, #5, #6	dynamic	51	no	no	no	no	no	no
	BMW	X2 (F39)	2017 -	#1, #2, #3, #5, #6	dynamic	53	no	no	no	no	no	no
	BMW	X3 (F25)	2010 - 2017	#1, #2, #3, #5, #6	dynamic	49	no	no	no	no	no	no
	BMW	X4 (F26)	2014 - 2018	#1, #2, #3, #5, #6	dynamic	49	no	no	no	no	no	no
	BMW	X5 (F15/F85)	2013 - 2018	#1, #2, #3, #5, #6	dynamic	49	no	no	no	no	no	no
	BMW	X6 (F16/F86)	2014 -	#1, #2, #3, #5, #6	dynamic	49	no	no	no	no	no	no
	Citroen	C4 Picasso II	2013 - 2018	#1, #2, #5, #6	dynamic	57	no	no	no	no	no	no
	Citroen	C5 Aircross	2018 -	#1, #2, #5, #6	dynamic	57	no	no	no	no	no	no
	Mazda	6 (GL)	2016 -	#1, #3, #5	static	56	no	no	no	no	no	CSC 3-03
	Mazda	CX-5 (KF)	2017 -	#1, #3, #5	static	56	no	no	no	no	no	CSC 3-03
	Mercedes	A-Klasse (BM177)	2018 -	#1, #5	dynamic	55	no	no	no	no	no	no
	Mercedes	B-Klasse (BM247)	2019 -	#1, #5	dynamic	57	no	no	no	no	no	no
	Mercedes	C-Klasse (BM204) Facelift	2011 - 2013	#1, #5	dynamic	48	no	no	no	no	no	no
	Mercedes	C-Klasse (BM205)	2014 - 2018	#1, #5	dynamic	48	no	no	no	no	no	no
	Mercedes	C-Klasse (BM205) Facelift	2018 -	#1, #5	dynamic	56	no	no	no	no	no	no
	Mercedes	CLA-Klasse (BM118)	2019 -	#1, #5	dynamic	57	no	no	no	no	no	no
	Mercedes	CLS-Klasse (BM257)	2018 -	#1, #5	dynamic	55	no	no	no	no	no	no
	Mercedes	E-Klasse (BM213)	2015 -	#1, #5	dynamic	55	no	no	no	no	no	no
	Mercedes	E-Klasse (BM238)	2015 -	#1, #5	dynamic	55	no	no	no	no	no	no
	Mercedes	GLC (BM253)	2015 -	#1, #5	dynamic	55	no	no	no	no	no	no
	Mercedes	GLE/GLS-Klasse (BM167)	2018 -	#1, #5	dynamic	57	no	no	no	no	no	no
	Mercedes	GLK-Klasse (BMX204) Facelift	2012 -	#1, #5	dynamic	48	no	no	no	no	no	no
	Mercedes	S-Klasse (BM222)	2013 -	#1, #5	dynamic	49	no	no	no	no	no	no
	Mercedes	S-Klasse Coupe (BM217)	2013 -	#1, #5	dynamic	51	no	no	no	no	no	no
	Mercedes	Sprinter (BM907/910)	2018 -	#1, #5	dynamic	57	no	no	no	no	no	no
	Mercedes	V-Klasse (BM447)	2014 -	#1, #5	dynamic	49	no	no	no	no	no	no
	Opel	Grandland X	2017 -	#1, #2, #3, #5, #6	dynamic	55	no	no	no	no	no	no
	Peugeot	5008 II	2017 -	#1, #2, #3, #5, #6	dynamic	55	no	no	no	no	no	no
	Peugeot	508 II	2018 -	#1, #2, #3, #5, #6	dynamic	55	no	no	no	no	no	no
	Porsche	Cayenne	2017 -	#1, #2, #3, #4, #5, #6	static	57	yes	no	no	no	no	CSC 3-02
	Seat	Ateca (KH)	2016 -	#1, #2, #3, #4, #5, #6	static	52	yes	no	no	no	no	CSC 3-02
	Seat	Tarraco (KN)	2019 -	#1, #2, #3, #4, #5, #6	static	56	yes	no	no	no	no	CSC 3-02
	Skoda	Kodiak (NS)	2017 -	#1, #2, #3, #4, #5, #6	static	52	yes	no	no	no	no	CSC 3-02
	Volvo	S60 III/V60 II	2018 -	#1, #2, #5, #6	dynamic	55	no	no	no	no	no	no
	Volvo	S90 II	2016 -	#1, #2, #5, #6	dynamic	55	no	no	no	no	no	no
	Volvo	XC60 II	2017 -	#1, #2, #5, #6	dynamic	55	no	no	no	no	no	no
	Volvo	XC90 II	2015 -	#1, #2, #5, #6	dynamic	55	no	no	no	no	no	no
	VW	Arteon (3H)	2017 -	#1, #2, #3, #4, #5, #6	static	53	yes	no	no	no	no	CSC 3-02
	VW	Passat (3G)	2015 - 2019	#1, #2, #3, #4, #5, #6	static	52	yes	no	no	no	no	CSC 3-02
new in V58	VW	Passat (CB)	2019 -	#1, #2, #3, #4, #5, #6	static	58	yes	no	no	no	no	CSC 3-02
	VW	Tiguan (AD)	2016 -	#1, #2, #3, #4, #5, #6	static	52	yes	no	no	no	no	CSC 3-02
	VW	Tiguan Allspace (BW)	2017 -	#1, #2, #3, #4, #5, #6	static	53	yes	no	no	no	no	CSC 3-02
	VW	Touareg (CR)	2018 -	#1, #2, #3, #4, #5, #6	static	56	yes	no	no	no	no	CSC 3-02

Table with columns: status version, manufacturer, model, year, calibration required by, calibration type, available since version, notes, equipment for positioning (CSC-Tool, Rear Cam Kit I Basic Profile), equipment for adjustment (radar reflector, magnetic laser CSC 4-02, Radar Kit II mirror adjusting device CSC 4-03). Rows include various car models from Mazda, Mercedes, Nissan, Opel, Peugeot, Porsche, Renault, Seat, Skoda, Suzuki, Toyota, and VW.

status version	manufacturer	model	year	calibration required by	calibration type	available since version	notes	equipment for positioning		equipment for adjustment		
								CSC-Tool	Rear Cam Kit I Basic Profile	radar reflector	magnetic laser CSC 4-02	Radar Kit II mirror adjusting device CSC 4-03
	VW	Caddy (SA)	2015 -	#1, #2, #3, #4, #5, #6	static	49		yes	no	CSC 4-01 EVO	no	no
	VW	CC (35)	2012 - 2017	#1, #2, #3, #4, #5, #6	static	46		yes	no	CSC 4-01/CSC 4-01 EVO	yes	no
	VW	Crafter (SZ/SY)	2017 -	#1, #2, #3, #4, #5, #6	static	52		yes	no	CSC 4-01/CSC 4-01 EVO	no	no
	VW	Golf 7 (5G/BA)	2012 -	#1, #2, #3, #4, #5, #6	static	46		yes	no	CSC 4-01/CSC 4-01 EVO	no	no
	VW	Passat (36)	2010 - 2014	#1, #2, #3, #4, #5, #6	static	46		yes	no	CSC 4-01/CSC 4-01 EVO	yes	no
	VW	Passat (3C)	2005 - 2010	#1, #2, #3, #4, #5, #6	static	46		yes	no	CSC 4-01/CSC 4-01 EVO	yes	no
	VW	Passat (3G)	2015 - 2019	#1, #2, #3, #4, #5, #6	static	48		yes	no	CSC 4-01/CSC 4-01 EVO	no	no
new in V58	VW	Passat (CB)	2019 -	#1, #2, #3, #4, #5, #6	static	58		yes	no	CSC 4-01/CSC 4-01 EVO	no	no
	VW	Passat CC (35)	2008 - 2012	#1, #2, #3, #4, #5, #6	static	46		yes	no	CSC 4-01/CSC 4-01 EVO	yes	no
	VW	Phaeton (3D)	2007 - 2016	#1, #2, #3, #4, #5, #6	static	50		yes	no	CSC 4-01/CSC 4-01 EVO	yes	no
	VW	Polo (6C)	2014 - 2017	#1, #2, #3, #4, #5, #6	static	49		yes	no	CSC 4-01/CSC 4-01 EVO	no	no
	VW	Polo (AW)	2017 -	#1, #2, #3, #4, #5, #6	static	53		yes	no	CSC 4-01/CSC 4-01 EVO	no	no
	VW	Sharan (7N)	2010 -	#1, #2, #3, #4, #5, #6	static	49		yes	no	CSC 4-01/CSC 4-01 EVO	yes	no
	VW	T6 (SG/SF)	2015 -	#1, #2, #3, #4, #5, #6	static	49		yes	no	CSC 4-01/CSC 4-01 EVO	no	no
	VW	T-Cross (C1)	2019 -	#1, #2, #3, #4, #5, #6	static	57		yes	no	CSC 4-01 EVO	no	no
	VW	Tiguan (AD)	2016 -	#1, #2, #3, #4, #5, #6	static	51		yes	no	CSC 4-01/CSC 4-01 EVO	no	no
	VW	Tiguan Allspace (BW)	2017 -	#1, #2, #3, #4, #5, #6	static	52		yes	no	CSC 4-01 EVO	no	no
	VW	Touareg (7P)	2010 - 2018	#1, #2, #3, #4, #5, #6	static	46		yes	no	CSC 4-01/CSC 4-01 EVO	no	no
	VW	Touareg (CR)	2018 -	#1, #2, #3, #4, #5, #6	static	56		yes	no	CSC 4-01 EVO	no	no
	VW	Touran (5T)	2015 -	#1, #2, #3, #4, #5, #6	static	50		yes	no	CSC 4-01/CSC 4-01 EVO	no	no
	VW	T-Roc (A1)	2017 -	#1, #2, #3, #4, #5, #6	static	55		yes	no	CSC 4-01/CSC 4-01 EVO	no	no

5 Vehicle Coverage Rear Radar V58

basic requirement: mega macs PC, 77, 66, 56, 42SE

calibration required:

- #1 after removal/installation radar sensor
- #2 after replacement radar sensor / change Lane Change Assistance ECU
- #3 after accident repair in the area of the radar sensor
- #4 suspension structure modified / adjusted
- #5 fault code
- #6 change rear bumper

status version	manufacturer	model	year	calibration required by	calibration type	available since version	equipment for positioning					equipment for calibration
							CSC-Tool	Rear Cam Kit I Basic Profile	Rear Cam Kit I Basic Panel	Rear Cam Kit I Addition Profile	positioning aid	radar reflector
	Audi	A3 (8V)	2012 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	A4 (8K)	2008 - 2015	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	A4 (8W)	2015 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	A5 (8T/8F)	2007 - 2016	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	A5 (F5)	2016 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	A6 (4A)	2018 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	A6 (4F)	2004 - 2011	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	A6 (4G)	2011 - 2018	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	A7 (4G)	2010 - 2018	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	A7 (4K)	2018 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	A8 (4H)	2010 - 2017	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	A8 (4N)	2017 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
new in V58	Audi	e-tron (GE)	2019 -	#1, #2, #3, #5, #6	static	58	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	Q2 (GA)	2016 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	Q3 (F3)	2018 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	Q5 (8R)	2008 - 2016	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	Q5 (FY)	2017 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	Q7 (4L)	2005 - 2015	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	Q7 (4M)	2015 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	Q8 (4M)	2018 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Audi	TT (FV)	2014 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Hyundai	Kona	2017 -	#3, #5	dynamic	57	no	no	no	no	no	no
	Hyundai	Santa Fe (DM)	2012 - 2018	#3, #5	dynamic	57	no	no	no	no	no	no
	Hyundai	Santa Fe (TM)	2018 -	#3, #5	dynamic	56	no	no	no	no	no	no
	Hyundai	Tucson(TL)	2015 -	#3, #5	dynamic	56	no	no	no	no	no	no
	Kia	Ceed (CD)	2018 -	#3, #5	dynamic	56	no	no	no	no	no	no
	Kia	Ceed (JD)	2012 - 2018	#3, #5	dynamic	57	no	no	no	no	no	no
	Kia	Pro Ceed JD)	2012 - 2018	#3, #5	dynamic	57	no	no	no	no	no	no
	Kia	Stonic (YB)	2017 -	#3, #5	dynamic	56	no	no	no	no	no	no
	Mazda	6 (GL)	2017 -	#1, #2, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	Mazda	CX-5 (KF)	2017 -	#1, #2, #5, #6	static	57	yes	yes	no	no	yes	CSC 4-04
	Mazda	CX-5 (KF)	2017 -	#1, #2, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
new in V58	Mazda	CX-3 (DK)	2015 - 2017	#1, #2, #5, #6	static	58	yes	yes	CSC 2-01	yes	no	CSC 4-06
new in V58	Mazda	6 (GJ)	2012 - 2016	#1, #2, #5, #6	static	58	yes	yes	CSC 2-01	yes	no	CSC 4-06
new in V58	Mazda	2 (DJ)	2015 -	#1, #2, #5, #6	static	58	yes	yes	CSC 2-01	yes	no	CSC 4-06
new in V58	Mazda	3 (BN)	2016 -	#1, #2, #5, #6	static	58	yes	yes	CSC 2-01	yes	no	CSC 4-06
new in V58	Mazda	3 (BM)	2013 - 2016	#1, #2, #5, #6	static	58	yes	yes	CSC 2-01	yes	no	CSC 4-06
new in V58	Toyota	Corolla	2018 -	#1, #2, #5	static	58	yes	yes	no	no	yes	CSC 4-05
	Toyota	C-HR	2016 -	#1, #2, #5	static	57	yes	yes	no	no	yes	CSC 4-05
new in V58	Toyota	Highlander	2018 -	#1, #2, #5	static	58	yes	yes	no	no	yes	CSC 4-05
new in V58	Toyota	Land Cruiser	2016 -	#1, #2, #5	static	58	yes	yes	no	no	yes	CSC 4-05
new in V58	Toyota	Prius	2016 -	#1, #2, #5	static	58	yes	yes	no	no	yes	CSC 4-05
new in V58	Toyota	RAV4	2016 - 2018	#1, #2, #5	static	58	yes	yes	no	no	yes	CSC 4-05
new in V58	Toyota	RAV4	2018 -	#1, #2, #5	static	58	yes	yes	no	no	yes	CSC 4-05
new in V58	Lexus	GS	2016 -	#1, #2, #5	static	58	yes	yes	no	no	yes	CSC 4-05
new in V58	Lexus	IS	2015 -	#1, #2, #5	static	58	yes	yes	no	no	yes	CSC 4-05
new in V58	Lexus	LC	2016 -	#1, #2, #5	static	58	yes	yes	no	no	yes	CSC 4-05
new in V58	Lexus	NX	2017 -	#1, #2, #5	static	58	yes	yes	no	no	yes	CSC 4-05
new in V58	Lexus	RC	2015 -	#1, #2, #5	static	58	yes	yes	no	no	yes	CSC 4-05
new in V58	Lexus	RX	2016 -	#1, #2, #5	static	58	yes	yes	no	no	yes	CSC 4-05
new in V58	Lexus	UX	2019 -	#1, #2, #5	static	58	yes	yes	no	no	yes	CSC 4-05
	VW	Arteon (3H)	2017 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	VW	CC (35)	2012 - 2017	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	VW	Passat (36)	2010 - 2014	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	VW	Passat (3G)	2015 - 2019	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
new in V58	VW	Passat (CB)	2019 -	#1, #2, #3, #5, #6	static	58	yes	yes	CSC 2-01	yes	no	CSC 4-06
	VW	Passat CC (35)	2008 - 2012	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	VW	T5 (7E/7F)	2009 - 2015	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	VW	T6 (SG/SF)	2015 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	VW	Tiguan (AD)	2016 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	VW	Tiguan Allspace (BW)	2017 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	VW	Touareg (7L)	2006 - 2010	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	VW	Touareg (7P)	2010 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	VW	Touareg (CR)	2018 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06
	VW	Touran (5T)	2015 -	#1, #2, #3, #5, #6	static	57	yes	yes	CSC 2-01	yes	no	CSC 4-06

6 Vehicle Coverage Laser Sensor V58

basic requirement: mega macs PC, 77, 66, 56, 42SE

adjustment required:

- #1 after removal / installation laser sensor
- #2 fault code
- #3 suspension structure modified / adjusted
- #4 lock carrier loosened / wrongly adjusted
- #5 bumper bracket loosened / wrongly adjusted
- #6 damage of bumper bracket / lock carrier

status version	manufacturer	model	year	calibration required by	available since version	equipment for positioning		equipment for adjustment
						CSC-Tool	system mount	panel
	Audi	A6 (4A)	2018 -	#1, #2, #3, #4, #5, #6	56	yes	yes	CSC 5-01
	Audi	A7 (4K)	2018 -	#1, #2, #3, #4, #5, #6	56	yes	yes	CSC 5-01
	Audi	A8 (4N)	2017 -	#1, #2, #3, #4, #5, #6	56	yes	yes	CSC 5-01
	Audi	Q8 (4M)	2019 -	#1, #2, #3, #4, #5, #6	56	yes	yes	CSC 5-01

HELLA GUTMANN SOLUTIONS GMBH

Am Krebsbach 2

79241 Ihringen

GERMANY

Phone: +49 7668 9900-0

Fax: +49 7668 9900-3999

info@hella-gutmann.com

www.hella-gutmann.com

© 2020 HELLA GUTMANN SOLUTIONS GMBH